



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed 


Report Date: 07/08/2014

Mine Name: Wolf Creek Mine	Permit Number: S/013/0016	Mine Status: Active
Operator Name: Leon & Sons Excavating LLC	Inspection Date: 06/25/2013	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: PM	Bond Amount: \$7,600
Attendee(s): none	Weather: Sunny, Dry	Bond Escalation: 03/31/2015
Inspection Purpose: Routine annual inspection		Prior Inspection: 09/10/2011

Conclusions and Recommendations

It is also the recommendation of the Division that the operator interim seed areas that are disturbed, but not fully reclaimed. Interim seeding helps with dust suppression and reduces the chance for weeds to establish in disturbed areas. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Permit fee is up to date, no transfers were requested, bond escalation is due as shown above .	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> No deficiencies were noted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No external drainage noted , but weather was dry	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> No deleterious material was noted on site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were minimal	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> No new revegetation was noted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M013-Duchesne/S0130016-WolfCreek/inspections/INSP-06252013.pdf





Overview of site looking northwest



Overview of site looking northwest



Overview of site looking north



Overview of site looking northeast